

SOFTWARE RELEASE NOTE: PLATINUM/ROTEM ONE 6/7.22.04



Summary

This release includes following features:

- Improvement on:
 - "Scale Layout" table view
 - Fix Scale Layout Set Table in Standard Mode
 - Bird Scale SD and CV presentation at the UI and Rotem Net WEB (4363)
 - Single Gender weighing precision
 - Zone Inlet minimum position
 - Tefen Dosing Pump Historical data presentation
 - Ventilation level stuck due to Attic (4324)
 - Precision Natural ventilation program change in exit conditions considering Tunnel entrance point conditions
 - Preventing bird weighing at negative days (4329)
 - History View Setting within New Flock activation
 - Bird Scale Settings: Manual Range Method editing values. Auto mode is blocked (4738)
 - WEB Dashboard presentation with more than two Light Dimmers
 - History View Setup presentation, while scrolling down
 - Bird Scale Settings: Manual Range Method editing values. Auto mode is blocked (4738)
 - WEB Dashboard presentation with more than two Light Dimmers
 - History View Setup presentation, while scrolling down
 - Loading Bird Curve Custom Table from SD Card when moving the settings from X.19.12 to X.22 (4964)
 - Average weight calculation according to gender grouping range limit

Release Specifications:

Product Name	Platinum, Rotem One/Pro
Software Version	PPRO 6. 22r04, PPT 7. 22r04
Supported Hardware	ARM CPU PRO/TOUCH
Communication Software	Rotem Net WEB 4.4.5
Release Date	08-Jun-21

Upgrade Issues – on Platinum settings copying after Firmware Upgrade

Starting from Platinum Version 5/6/7.19, the not copied tables list will be presented through the Controller's User Interface.:

Note: When loading setting saved in a version prior to X.22.04 the following tables will not be loaded:

- Scale/Bird Weight Broiler
- Scale/Bird Weight Breeder Male
- Scale/Bird Weight Breeder Female

SW Update Issues – on Platinum Touch & Rotem One

When updating Platinum Touch / Rotem One SW the following order should be kept for proper indication at Touch Screen:

- 1st update Platinum Touch / Rotem One UI SW using USB disk
- 2nd update Platinum Controller SW using SD card